Incident Information Release

SAFEWORK NSW

01/2020

Fall through plastic skylight panel

6 December 2019

Incident overview

A 31-year-old man suffered critical injuries when he fell more than 10 meters through a plastic roof-panel at a school in Croydon.



Incident Location

The investigation

- SafeWork NSW inspectors responded to the incident.
- SafeWork NSW commenced an investigation to determine the cause and circumstances of the incident.

The information contained in this publication is based on knowledge and understanding at the time of writing. No conclusions should be drawn from the information in this publication about the cause of the incident or the culpability of any party.



24/01/2020

Incident Information Release



SAFEWORK NSW

24/01/2020

Safety Information

Businesses are reminded of their duty to identify hazards and manage risks to health and safety in accordance with the provisions of the <u>Work Health and Safety Act 2011</u> and <u>Work Health and Safety Regulation 2017</u>.

Consider 'reasonably practicable' control measures to manage the risk of falls.

Before starting work on a roof, carry out an inspection to determine:

- the condition of sheeting that shouldn't be walked on, such as a skylight, plastic or asbestos cement sheeting
- the presence and integrity of safety wire mesh
- the suitability of anchor points.

To determine if surfaces are safe to walk on, check the surrounding material, how it's fixed and whether it's brittle.

Make sure you:

- plan the work to avoid walking on brittle material
- work from a solid construction to avoid standing on the roof
- use temporary work platforms, such as crawling boards and ladders
- install barriers, such as guardrails, covers, and warning signs
- install safety mesh
- use a scaffold or scissor/boom lift
- use an adjustable fall-arrest system, such as a harness, with proper anchor points train workers how to use it.

More information

- <u>Code of practice for managing the risk of falls at workplaces</u>
- Working at heights

The information contained in this publication is based on knowledge and understanding at the time of writing. No conclusions should be drawn from the information in this publication about the cause of the incident or the culpability of any party.